
| City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form | | Page 1 of 3 |
|--|--|---|
| Sewershed : Gwynn Falls | Company : <u>URS</u> | Date: 09/23/2008 |
| Test to be Performed : Smoke : X Dyed Water : | Ground Condition : Dry : X Damp : Wet : | Supervisor : Ryan Lamont |
| Manhole ID: S03QQ 028MH | Test ID: S1032-022037 | Notifications (Residents, Fire, 311) : Yes |


Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



| City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form | | Page 2 of 3 |
|--|--|--|
| Sewershed : Gwynn Falls | Company : <u>URS</u> | Date: 09/23/2008 |
| Test to be Performed : Smoke : X Dyed Water : | Ground Condition : Dry : X Damp : Wet : | Supervisor : Ryan Lamont |
| Manhole ID: S03QQ_028MH | Test ID: S1032-022037 | Notifications (Residents, Fire, 311) : Yes |

Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Storm Manhole; Smoke: Medium; Status: Public ROW


Landscape



Defect



ID



Location: N/A; Type: Catch Basin; Smoke: Heavy; Status: Public ROW

Landscape




Defect



| City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form | | Page 3 of 3 |
|--|--|---|
| Sewershed : Gwynn Falls | Company : <u>URS</u> | Date : <u>09/23/2008</u> |
| Test to be Performed : Smoke : X Dyed Water : | Ground Condition : Dry : X Damp : Wet : | Supervisor : Ryan Lamont |
| Manhole ID: S03QQ 028MH | Test ID: S1032-022037 | Notifications (Residents, Fire, 311) : Yes |

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Storm Manhole; Smoke: Heavy; Status: Public ROW

Landscape



Defect

